



VIN

MECHANICAL EMISSIONS SERVICES LLC
22 East 7th Street
Calexico, CA 92231
(619) 845-1299



Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

VIN	3CZRU6H5XLM717516		Year	2020	
Mfg In	MEXICO	Make	Honda	Owner's Name	MARIA GUADALUPE PEREZ BARRON
Model	HR-V	License Plate	C4	Odometer (mi)	61055 98258.25370 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MEC8-00000009	Geo Location	Latitude: 32.671667, Longitude: -115.497500	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	8 Zamantha Trucios	Inspector Signature	Zamantha Trucios	
Catalyst Monitor	PASS	Overall Test Result	PASS	EI ITN	X20241107480458	Date	2024/11/13	Expires: 2025/02/13



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

