



MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299




Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

VIN	5J8TB3H5XHL003749	Year	2017
Mfg In	UNITED STATES	Make	Acura
Model	RDX	License Plate	K2 NONE
Owner's Name	AGENCIA ADUANAL INTERNACIONAL DE COMERCIO EXT		
Odometer (mi)	152562	245524.12908 km	

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET1-00000006	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	03 Sara Corona	Inspector Signature	<i>Sara Corona</i>	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEl ITN	X20241113003749	Date	2024/11/13	
							Expires: 2025/02/13	



Semarnat Autorization Letter
 No. SRA.600/DPRA/DPMR/377/2022
 CA BAR 97 GEN3 and/or Drew Technologies IMClean
 ESP 10400-89 Software Version: 16028007727838
 To verify this Certificate please go to:
www.mecemissions.com

