



**MECHANICAL EMISSIONS SERVICES LLC**  
**6225B Alameda Avenue**  
**El Paso, TX 79905**  
**(619) 845-1299**




Cert Number

Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

VIN	3N1AB7AP2KY429543	Year	2019
Mfg In	MEXICO	Make	Nissan
Model	Sentra	License Plate	K2 NONE
Owner's Name	NORMA GRACIELA ZAVALA CUEVAS		
Odometer (mi)	96097	154652.74598 km	

**Monitoring Information and Certificate**

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET1-0000011	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	03 Sara Corona	Inspector Signature	<i>Sara Corona</i>	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEl ITN	X20241113429543	Date	2024/11/13	
							<b>Expires: 2025/02/13</b>	



Semarnat Autorization Letter  
 No. SRA.600/DPRA/DPMR/377/2022  
 CA BAR 97 GEN3 and/or Drew Technologies IMClean  
 ESP 10400-89 Software Version: 16028007727838  
 To verify this Certificate please go to:  
[www.mecemissions.com](http://www.mecemissions.com)

