



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3N1CN8DV8LL894830		Year	2020	
Mfg In	MEXICO	Make	Nissan	Owner's Name	AGENCIA ADUANAL INTERNACIONAL DE COMERCIO EXTERIOR LG S DE RL DE CV
Model	Versa	License Plate	k2 none	Odometer (mi)	61164 98433.67176 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET1-00001744	Geo Location	Latitude: 31.765747, Longitude: -106.411451	
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	03 Sara Corona	Inspector Signature	Sara Corona	
Catalyst Monitor	PASS	Overall Test Result	PASS	EEI ITN	X20241226894830	Date	2024/12/26	Expires: 2025/03/26



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

