



VIN

MECHANICAL EMISSIONS SERVICES LLC
6225B Alameda Avenue
El Paso, TX 79905
(619) 845-1299



Cert Number


Powered by -- Formula 1 Auto Repair -- (BAR NBR RC 00305923)

Vehicle Information

VIN	3VW167AJ4HM225711		Year	2017	
Mfg In	MEXICO	Make	Volkswagen	Owner's Name	ELIZABETH EDITH DIAZ ESPINOZA
Model	Jetta	License Plate	K4 NONE	Odometer (mi)	91247 146847.44698 km

Monitoring Information and Certificate

Misfire Monitor	PASS	Fuel System Monitor	PASS	Cert Number	MET1-00001751	Geo Location	Latitude: 31.765747, Longitude: -106.411451
Comprehensive Monitor Catalyst	PASS	O2 Sensor Monitor	PASS	Inspector Name	03 Sara Corona	Inspector Signature	Sara Corona
Catalyst Monitor	PASS	Overall Test Result	PASS	EET ITN	X20241226225711	Date	2024/12/26 Expires: 2025/03/26



Semarnat Authorization Letter
No. SRA.600/DPRA/DPMR/377/2022
CA BAR 97 GEN3 and/or Drew Technologies IMClean
ESP 10400-89 Software Version: 16028007727838
To verify this Certificate please go to:
www.mecemissions.com

